


Project Case Study

Project

Queen Elizabeth Hospital
28 Woodville Road
Woodville South SA 5011



Project Summary

Substrate

Terrazzo Flooring 200^{m2}

Surface Preparation

Dustless diamond grinding, Epoxy Primer followed by a 3mm Epoxy screed

System

Broadcast Vinyl Flake into screed. Top coat with 100% clear epoxy and water based matt urethane.

Project Description

When the Queen Elizabeth Hospital set out to re do their Operating Theatre floors, there was a great emphasis on limiting the shut down time of the 3 theatre's and to have the project completed with no interruptions to the other adjoining theatres. The existing terrazzo flooring had significantly deteriorated over time; the pitting was very unhygienic and it had created difficulty in cleaning and maintenance.

Dustless diamond grinding was considered to be the best preparation and a vinyl chip flooring system was deemed an ideal solution. This satisfied the requirements of:

- The lifespan of at least 10+ years,
- Must be hygienic,
- Able to be coved,
- Zero-tolerance for residual odours upon completion,
- Able to withstand wet environments,

The Vinyl Chip Flooring system was chosen because it satisfied all of the clients' needs. It is also extremely flexible with colours and design. There are no seams to harbour dirt, bacteria or fungus. The finish is long lasting and easily cleaned. The floor can be scrubbed repeatedly without damage to the finish. What used to take the client 20 minutes on hands and knees to scrub clean will now be done in under half the time - only needing a mop and soapy water! The reduction in cleaning is attributed to the zero porosity of Vinyl Chip Flooring Industrial Flooring.

Within hours of completion there were no detectable smells as the products used contained 100% solids, making the theatre ready for handover the next morning.

After its completion, the staff loved the aesthetic qualities of the floor, with requests as to when we could start to replace the rest of the terrazzo! It was a success.

Another satisfied Poly Tech customer.

The concrete protection & restoration specialists
South Australia, Tasmania, Victoria & Northern Territory

Poly-Tech Industrial Services

Unit 1, 100-104 Hayward Ave, Torrensville SA 5031 www.poly-tech.com.au sales@poly-tech.com.au
Ph (08) 8346 4111 Fax (08) 8346 4333

poly-tech

COMPLETE ACID PROTECTION